

MATERIALS SAFETY DATA SHEET

PRODUCT NAME: HOT MELT CARPET SEAMING TAPE

MANUFACTURERS

NAME XI' AN XIANGSEN CARPET MATERIALS CO.,LTD

SYNONYMS: Heat Bond Seaming Tape/ Carpet seaming tape

ADDRESS: No 8 West HongQing industrial Zone Xi'an 710025 China

CAS NUMBER: None EMERGENCY

TELEPHONE NO: +86-29-83313673

DATE PREPARED: OCT 15, 2011 INFORMATION

PREPARED BY: Kevin TECH LINE +86-29-83313673

I. HAZARDOUS INGREDIENTS

None per OSHA Regulations: 29CFR1910.1200

None per SARA Title III , Section 313 and TCA 40 CRF 372

Hazardous Components: None

Non Hazardous Components: Resin, Polymers, Inert Ingredients

II. PHYSICAL DATA

BOILING POINT ((760 mm, Hg)	N/A	SPECIFIC GRAVITY (H ₂ O=1)	0.96
VAPOR PRESSURE AT 20°C	N/A	VAPOR DENSITY (AIR=1)	N/A
SOLUBILITY IN WATER % BY WT.	Insoluble	PERCENT VOLATILES(BY VOLUME)	0
EVAPORATION RATE (BUTYL ACETATE = 1)	N/A	pH	N/A

APPEARANCE AND ODOR: Odorless, milky white/amber color solid adhesive covering a woven fabric scrim and paper.

III. FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (TEST METHOD)	N/A	AUTOIGNITION TEMPERATURE	N/A
FLAMMABLE LIMITS IN AIR, % BY VOLUME	N/A	LOWER N/A (LEL)	UPPER N/A (UEL)
EXTINGUISHING MEDIA:	Foam, Dry Chemical, CO ₂ .		
SPECIAL FIRE FIGHTING PROCEDURES:	None		
UNUSUAL FIRE AND EXPLOSION HAZARDS:	None		

IV. REACTIVITY DATA

STABILITY: Stable

CONDITIONS TO AVOID: Excessive Heat

INCOMPATIBILITY:
(MATERIALS TO AVOID) Strong Oxidizing Agents

HAZARDOUS DECOMPOSITION PRODUCTS: Combustion Products.

HAZARDOUS POLYMERIZATION: Will Not Occur

V. HEALTH HAZARD DATA

PRIMARY ROUTE OF ENTRY: N/A

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE: Overheating/charring may generate irritating vapors.

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE: Molten adhesive will cause skin burns.

EFFECT OF OVEREXPOSURE: None Known

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: None Known

HEALTH HAZARDS (Acute and Chronic): None

CARCINOGENICITY: This product contains No Carcinogens as listed by NTP, IRAC and OSHA

EMERGENCY AND FIRST AID PROCEDURES:

INHALATION: If exposed to fumes from overheating/charring or combustion of adhesive, remove to fresh air.

EYES: Flush with large amount of cool water. Contact physician if irritation persists.

SKIN: If burned by contact with molten adhesive, cool as quickly as possible with water. Do not attempt to remove stuck adhesive from skin. Burns should be treated as thermal burns. Obtain medical attention for burns.

INGESTION: Material is not likely to be ingested. Consult a physician if ingested.

VI. PRECAUTIONS FOR SAFE HANDLING AND USE

PRECAUTION FOR HANDLING AND STORING: Keep out of reach of children. Avoid excessive heat and freezing.

OTHER PRECAUTIONS: Prevent or mitigate the generation of irritating vapors from overheating/charring of adhesive by insuring the iron is clean and operating at proper temperatures.

VII. SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED

Not applicable for product in purchase form.

WASTE DISPOSAL METHOD

Dispose according to Federal, State and Local regulations.

VIII. CONTROL MEASURES

RESPIRATORY PROTECTION: Not required.

VENTILATION: Normal room ventilation with fans if necessary.

PROTECTIVE GLOVES: Not required.

EYE PROTECTION: Safety glasses recommended.

WORK/HYGIENE PRACTICES: General hygiene and safe handling procedures are believed to be generally applicable.